


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-212	Smoke	8/4/2009	ADS/TM	S17C_022MH	Dry	Yes	1,001.69



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-212	Smoke	8/4/2009	ADS/TM	S17C__022MH	Dry	Yes	1,001.69

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S17C__034G1	S17C__034UN	S17C__032MH	548.721	10
S17C__005G1	S17C__005MH	S17C__022MH	148.683	8
S17C__022G1	S17C__022MH	S15C__040MH	256.525	8
S15C__040G1	S15C__040MH	S15C__018MH	47.7639	8

Observations & Photos

Obs_ID S1028-212-OB01

Address 2316 Edmondson Ave

Status Private

Source Cleanout

Location Yard - back

Nearest MH S17A__005MH

Comments Smoke from cleanout in back yard. 2316 Edmondson Ave.



Picture \S1028-212-OB01-P01.jpg

Comments Back of house, 2316 Edmondson Ave.

Obs_ID S1028-212-OB02

Address 2416 Edmondson Ave

Status Private

Source Cleanout

Location Yard - back

Nearest MH S17C__005MH

Comments Smoke from above-grade cleanout in back yard. 2416 Edmondson Ave.



Picture \S1028-212-OB02-P01.jpg

Comments Back of house, 2416 Edmondson Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-212	Smoke	8/4/2009	ADS/TM	S17C__022MH	Dry	Yes	1,001.69

Obs_ID S1028-212-OB03

Address 2500 Edmondson Ave


Status Private

Source Foundation Drain

Location Alley

Nearest MH S17C__005MH

Comments Smoke from foundation drain in alley next to church. 2500 Edmondson Ave.



Picture \S1028-212-OB03-P01.jpg

Comments Side of church, 2500 Edmondson Ave. looking towards Warwick Ave.

Obs_ID S1028-212-OB05

Address 2523 Arunah Ave


Status Private

Source Service Lateral

Location Paved concrete

Nearest MH S17C__022MH

Comments Smoke from service lateral under paved concrete in back yard. 2523 Arunah Ave.



Picture \S1028-212-OB05-P01.jpg

Comments Back of house, 2523 Arunah Ave.

Obs_ID S1028-212-OB04

Address 2500 Edmondson Ave


Status Private

Source Foundation Drain

Location Alley

Nearest MH S17C__005MH

Comments Smoke from foundation drain in alley next to church. 2500 Edmondson Ave.



Picture \S1028-212-OB04-P01.jpg

Comments Side of church, 2500 Edmondson Ave. looking towards Warwick Ave.

Obs_ID S1028-212-OB06

Address 2523 Arunah Ave


Status Private

Source Service Lateral

Location Yard - back

Nearest MH S17C__022MH

Comments Smoke from service lateral in back yard. 2523 Arunah Ave.



Picture \S1028-212-OB06-P01.jpg

Comments Back of house, 2523 Arunah Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-212	Smoke	8/4/2009	ADS/TM	S17C__022MH	Dry	Yes	1,001.69

Obs_ID S1028-212-OB07

Address 2525 Arunah Ave


Status Private

Source Service Lateral

Location Paved concrete

Nearest MH S17C__022MH

Comments Smoke from service lateral under paved concrete in back yard. 2525 Arunah Ave.



Picture \S1028-212-OB07-P01.jpg

Comments Back of house, 2525 Arunah Ave.